


# South Focus Area


**Public Comments** 


Aloha Street to N. 50th Street




SR 99 @ Bridge Way North









### An Overview of Public Comments

The following comments were provided by the public as well as businesses and community organizations along the corridor.

Aurora Bridge (George Washington Memorial Bridge)

- 1. Provide wider sidewalks, preferably 8' to 10' wide
- 2. Safety concerns about existing pedestrian facility and suggested pedestrian tunnel underneath the Aurora Bridge
- 3. Look at solutions regarding head-on collision risks
- 4. Retrofit the bridge
- 5. Reduce bridge speed to 25 mph and provide better speed enforcement
- 6. Add a narrow median barrier

### Access

- 7. Modify side street access in the vicinity of N. 38<sup>th</sup>, including improvements for freight access
- 8. Add a northbound drop lane at Bridge Way N.
- 9. Look at east/west bicycle access across Aurora (specifically at N. 38<sup>th</sup>, N. 40<sup>th</sup>, N. 46<sup>th</sup> Streets)
- 10. Improve northbound ramp connections to and from Aurora Avenue to N. 38<sup>th</sup>, N. 46<sup>th</sup>, and N. 50<sup>th</sup> Street interchanges.
- 11. Improve access to Aurora Ave. southbound at N. 50<sup>th</sup> Street
- 12. Provide better east/west access at Aloha Street, Roy Street, and Denny Way
- 13. Look at the entrances and exits to/from SR 99 in the Queen Anne area
- 14. Consider restoring pedestrian and vehicular traffic connections in the South Lake Union/Queen Anne/Uptown neighborhoods

#### Non-Motorized

- 15. Look at improvements to make biking along Aurora more hospitable
- 16. Develop an exclusive bicycle crossing in the vicinity of N. 43rd.
- 17. Don't build an overpass at Galer, look at building the overpass across Aurora to complete the Interurban trail connection
- 18. Build overpass further north in closer proximity to Aloha Inn
- 19. Look at continuous pedestrian walkways on both east and west sides of Aurora

## Other Safety Issues

- 20. Concerned about safety by Canlis Restaurant
- 21. Don't want trees out of the clear zone
- 22. Provide better directional signage
- 23. Install transit stops on Aurora Ave at Bridge Way N. 24. Improve sight distance and merge lane geometrics at N. 50<sup>th</sup>
- 25. Look at clear zones and vehicle/pedestrian conflicts 26. Install traffic calming measures on residential streets that lead to the N. 38<sup>th</sup>, N. 46<sup>th</sup> and N. 50<sup>th</sup> St.
- intersections 27. Provide additional speed limit enforcement
- 28. Address safety concerns in the Halladay Street/Raye St. area
- 29. Provide better security for pedestrian undercrossings

## **Transit**

- 30. Add a bus stop in front of Aloha Inn
- 31. Install transit stops on Aurora Ave at Bridge Way N.
- 32. Add bus lanes between N. 50<sup>th</sup> St. through Aurora Ave. Bridge

# **Mobility**

- 33. Study Bridge Way N. to address auto, truck, and bicycle flow
- 34. Look at add/drop lane on Bridge Way at N. 38<sup>th</sup>/39<sup>th</sup> Streets and/or a transit-use only lane
- 35. Redesign the southbound Freemont Avenue on-ramp to better connect to the Aurora Bridge
- 36. Concerned about northbound traffic overflow
- 37. Look at an add/drop lane at Raye St.

## Other

- 38. Make sure project improvements meet the American's with Disabilities Act (ADA) guidelines
- 39. Need signage marking the exit to Fremont
- 40. Need better signage for the N. 39<sup>th</sup> St. exit





